

FIG. 1




FIG. 2

2/15




FIG. 3
RELATED ART




FIG. 4
RELATED ART

3/15




FIG. 5
RELATED ART




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20





FIG. 21

— Before sealing
 - - - Heat treatment performed once
 - - - Heat treatment performed twice
 - - - Heat treatment performed three times
 Heat treatment performed four times

FIG. 22






FIG. 23

15/15




FIG. 24




FIG. 25